



Change in Design & Service: FF5418 & FS1298

Cummins Filtration recently changed the design and service installation procedures for the **FF5418** fuel filter for Ford Super Duty 7.3L diesel engine, model year 1998-2003, and for the **FS1298** fuel water separator for Ford 7.3L diesel engine model year 1994-2000.

To enable the installation of the filter on the unique OEM interface, a new interface "Cap" was designed to replace the original OEM part. The new cap will be included in the FF5418 and FS1298 packaging.

This new cap requires a one time alteration in the service installation procedure of the filter. Individual packing of the filter will include the step by step instructions for service.

Change in the design is permanent effective April 1, 2008.

For more information, visit cumminsfiltration.com

MB10020

©2008 Cummins Filtration
Printed in U.S.A.